

03500.015208.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

**In re Patent of:**

ICHIRO NOMURA ET AL.

Appln. No.: 09/809,055

Filed: March 16, 2001

For: METHOD AND APPARATUS FOR  
MANUFACTURING IMAGE  
DISPLAYING APPARATUS

U.S. Patent No.: 6,848,961 B2

Issued: February 1, 2005

**Certificate  
JUL 22 2005  
of Correction**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/20/2005 SSITHIB1 00000061 6848961

01 FC:1811


100.00 NP

JUL 25 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee  
for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by  
telephone at (212) 218-2100. All correspondence should continue to be directed to our  
address given below.

Respectfully submitted,



\_\_\_\_\_  
Leonard P. Diana  
Attorney for Patentees  
Registration No. 29,296

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200

NY\_Main 511236v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 1 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [57] ABSTRACT:

Line 6, "substrate. While," should read --substrate, while--.

COLUMN 2:

Line 22, "'FP'" should read --as "FP")--;  
Line 28, "requires" should read --requires a--;  
Line 30, "inside" should read --the inside--;  
Line 31, "10-6 Pa" should read 10<sup>-6</sup> Pa; and  
Line 40, "are" should be deleted.

COLUMN 3:

Line 3, " a manufacturing" should read --manufacturing--;  
Line 12, "connected" should read --are connected--;  
Line 16, "whereby" should read --thereby--;  
Line 27, "a gettering" should read --performing a gettering-- and  
"is performed" should be deleted; and  
Line 45, "whereby" should read --thereby--.

COLUMN 4:

Line 61, "a of" should read --another mode of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 2 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 5:**

Line 36, "connected" should read --are connected--;  
Line 41, "whereby" should read --thereby--;  
Line 47, "are disposed" should be deleted;  
Line 52, "a gettering" should read --performing a gettering-- and  
"is performed" should be deleted; and  
Line 58, "Secondary," should read --Secondarily,--.

**COLUMN 6:**

Line 5, "whereby" should read --thereby--.

**COLUMN 8:**

Line 34, "arrange" should read --arranged--;  
Line 44, "region" should read --the region--;  
Line 45, "air-tight" should read --airtight--; and  
Line 46, "wiring" should read --the wiring--.

**COLUMN 9:**

Line 29, "under setting" should read --where--;  
Line 30, "into" should read --is under--;  
Line 31, "under setting" should read --where--;  
Line 32, "into" should read --is under--; and  
Line 52, "means" should read --is defined as--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 3 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 10:**

Line 5, "gage;" should read --gauge;-- and  
"an drawing" should read --a drawing--;

Line 48, "that" should read --in which--; and

Line 60, "that" should read --in which--.

**COLUMN 11:**

Line 27, "(en" should read --(an--;

Line 31, "case" should read --case in which--;

Line 32, "member" should read --members--;

Line 39, "hardly deform" should read --more difficult to deform--; and

Line 44, "case" should read --case in which--.

**COLUMN 12:**

Line 19, "with" (second occurrence) should read --with substances--;

Line 21, "apply" should read --application--;

Line 35, "C<sub>n</sub>H<sub>2</sub>n<sup>+2</sup> of" should read --C<sub>n</sub>H<sub>2</sub>n<sup>+2</sup>,--;

Line 37, "C<sub>n</sub>H<sub>2</sub>n etc." should read --C<sub>n</sub>H<sub>2</sub>n,--; and

Line 54, "by such as" should read --of--.

**COLUMN 13:**

Line 1, "gases" should read --gas--; and

Line 27, "is used." should read --are used.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 4 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 14:

Line 65, "replace" should read --replacement--.

### COLUMN 15:

Line 43, "used, however," should read --used. However,--.

### COLUMN 17:

Line 50, "moves" should read --move--; and

Lines 64-65, "thereby vacuum exhausting" should read --thereby creating  
vacuum--.

### COLUMN 18:

Line 11, "carried in" should read --carried into--;

Line 16, "subject to" should read --subjected to--; and

Line 52, "range of" should read --range where it is--.

### COLUMN 19:

Line 12, "a evaporable" should read --an evaporable--;

Line 26, "a electrostatic" should read --an electrostatic--; and

Line 37, "fist" should read --first--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 5 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 20:

Line 24, "in" should read --into--;  
Line 27, "is arranged" should read --are arranged--;  
Line 29, "contacts" should read --contact--;  
Line 32, "toward inside" should read --toward the inside--; and  
Line 58, "withing" should read --within--.

## COLUMN 21:

Line 1, "carried in" should read --being carried into--;  
Line 5, "inside" should read --the inside--;  
Line 14, "proceed" should read --proceed with--;  
Line 27, "AS" should read --As--;  
Line 28, "proceed" should read --proceed with--; and  
Line 51, "207" should read --2207--.

## COLUMN 22:

Line 5, "one of substrates on both substrates" should read --one of the substrates--;  
Line 42, "the devices" should read --devices--;  
Line 47, "existing" should read --causing--;  
Line 48, "technique" should read --steps--;  
Line 50, "sides. Embodiments" should read --sides. ¶(no indent)  
EMBODIMENTS-- and "The" should read --¶ The--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 6 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 23:**

Line 27, "caused" should read --be caused--; and  
Line 55, "to" should be deleted.

**COLUMN 24:**

Line 9, "to" should be deleted.

**COLUMN 25:**

Line 32, "the activation" should read --an activation--.

**COLUMN 26:**

Line 44, "that" should read --wherein--.

**COLUMN 27:**

Line 30, "IF" should read --If--.

**COLUMN 28:**

Line 12, "The" should read --An--; and  
Line 29, "as in the same manner in" should read --in the same manner as in--.

**COLUMN 29:**

Line 31, "on" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 7 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 30:**

Line 11, “ $Sd = SO \times [1+(d/L)]^{\frac{1}{2}}$ ” should read -- $Sd = SO \times [1+(d/L)^2]^{\frac{1}{2}}$ --.

**COLUMN 36:**

Line 33, “an” should read --a--.

**COLUMN 37:**

Line 62, “manufacture.” should read --manufactured--.

**COLUMN 38:**

Line 3, “manufacture” should read --manufacturing--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 1 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [57] ABSTRACT:

Line 6, "substrate. While," should read --substrate, while--.

COLUMN 2:

Line 22, "'FP'" should read --as "FP"--;  
Line 28, "requires" should read --requires a--;  
Line 30, "inside" should read --the inside--;  
Line 31, "10-6 Pa" should read 10<sup>6</sup> Pa; and  
Line 40, "are" should be deleted.

COLUMN 3:

Line 3, " a manufacturing" should read --manufacturing--;  
Line 12, "connected" should read --are connected--;  
Line 16, "whereby" should read --thereby--;  
Line 27, "a gettering" should read --performing a gettering-- and  
"is performed" should be deleted; and  
Line 45, "whereby" should read --thereby--.

COLUMN 4:

Line 61, "a of" should read --another mode of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page



JUL 25 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 2 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 5:**

Line 36, "connected" should read --are connected--;  
Line 41, "whereby" should read --thereby--;  
Line 47, "are disposed" should be deleted;  
Line 52, "a gettering" should read --performing a gettering-- and  
"is performed" should be deleted; and  
Line 58, "Secondary," should read --Secondarily,--.

**COLUMN 6:**

Line 5, "whereby" should read --thereby--.

**COLUMN 8:**

Line 34, "arrange" should read --arranged--;  
Line 44, "region" should read --the region--;  
Line 45, "air-tight" should read --airtight--; and  
Line 46, "wiring" should read --the wiring--.

**COLUMN 9:**

Line 29, "under setting" should read --where--;  
Line 30, "into" should read --is under--;  
Line 31, "under setting" should read --where--;  
Line 32, "into" should read --is under--; and  
Line 52, "means" should read --is defined as--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 3 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 10:

Line 5, "gage;" should read --gauge;-- and  
"an drawing" should read --a drawing--;

Line 48, "that" should read --in which--; and

Line 60, "that" should read --in which--.

## COLUMN 11:

Line 27, "(en" should read --(an--;

Line 31, "case" should read --case in which--;

Line 32, "member" should read --members--;

Line 39, "hardly deform" should read --more difficult to deform--; and

Line 44, "case" should read --case in which--.

## COLUMN 12:

Line 19, "with" (second occurrence) should read --with substances--;

Line 21, "apply" should read --application--;

Line 35, "C<sub>n</sub>H<sub>2</sub>n<sup>+2</sup> of" should read --C<sub>n</sub>H<sub>2</sub>n<sup>+2</sup>,--;

Line 37, "C<sub>n</sub>H<sub>2</sub>n etc." should read --C<sub>n</sub>H<sub>2</sub>n,--; and

Line 54, "by such as" should read --of--.

## COLUMN 13:

Line 1, "gases" should read --gas--; and

Line 27, "is used." should read --are used.--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 4 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 14:

Line 65, "replace" should read --replacement--.

## COLUMN 15:

Line 43, "used, however," should read --used. However,--.

## COLUMN 17:

Line 50, "moves" should read --move--; and

Lines 64-65, "thereby vacuum exhausting" should read --thereby creating  
vacuum--.

## COLUMN 18:

Line 11, "carried in" should read --carried into--;

Line 16, "subject to" should read --subjected to--; and

Line 52, "range of" should read --range where it is--.

## COLUMN 19:

Line 12, "a evaporable" should read --an evaporable--;

Line 26, "a electrostatic" should read --an electrostatic--; and

Line 37, "fist" should read --first--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 5 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 20:

Line 24, "in" should read --into--;  
Line 27, "is arranged" should read --are arranged--;  
Line 29, "contacts" should read --contact--;  
Line 32, "toward inside" should read --toward the inside--; and  
Line 58, "withing" should read --within--.

## COLUMN 21:

Line 1, "carried in" should read --being carried into--;  
Line 5, "inside" should read --the inside--;  
Line 14, "proceed" should read --proceed with--;  
Line 27, "AS" should read --As--;  
Line 28, "proceed" should read --proceed with--; and  
Line 51, "207" should read --2207--.

## COLUMN 22:

Line 5, "one of substrates on both substrates" should read --one of the substrates--;  
Line 42, "the devices" should read --devices--;  
Line 47, "existing" should read --causing--;  
Line 48, "technique" should read --steps--;  
Line 50, "sides. Embodiments" should read --sides. ¶(no indent)  
EMBODIMENTS-- and "The" should read --¶ The--.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page



# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 6 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 23:

Line 27, "caused" should read --be caused--; and  
Line 55, "to" should be deleted.

## COLUMN 24:

Line 9, "to" should be deleted.

## COLUMN 25:

Line 32, "the activation" should read --an activation--.

## COLUMN 26:

Line 44, "that" should read --wherein--.

## COLUMN 27:

Line 30, "IF" should read --If--.

## COLUMN 28:

Line 12, "The" should read --An--; and  
Line 29, "as in the same manner in" should read --in the same manner as in--.

## COLUMN 29:

Line 31, "on" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,848,961 B2

DATED : February 1, 2005

INVENTOR(S) : ICHIRO NOMURA ET AL.

Page 7 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 30:**

Line 11, " $Sd = SO \times [1 + (d/L)]^{1/2}$ " should read -- $Sd = SO \times [1 + (d/L)^2]^{1/2}$ --.

**COLUMN 36:**

Line 33, "an" should read --a--.

**COLUMN 37:**

Line 62, "manufacture." should read --manufactured.--.

**COLUMN 38:**

Line 3, "manufacture" should read --manufacturing--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO. US 6,848,961 B2**

No. of add'l. copies  
@ 30¢ per page

